

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number 46846	2. Page 1 of 1	3. Emergency Response Phone (505) 452-2710	4. Manifest Tracking Number 008037596 FLE				
5. Generator's Name and Mailing Address Clean Harbors Lone Mountain LLC 2849 North New York Street Wichita, KS 67219 (316) 269-7400			Generator's Site Address (if different than mailing address) SAME						
6. Transporter 1 Company Name U.S. Bulk Transportation Inc			U.S. EPA ID Number PA1987347515						
7. Transporter 2 Company Name			U.S. EPA ID Number						
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40355 S County Road 236 Wameka, OK 73860 Facility's Phone: (580) 657-3500			U.S. EPA ID Number OKD065438376						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
	X	1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III		No.	Type	EST 16	/	F001 F002 F003 F004 F005	
		2.							
		3.							
		4.							
14. Special Handling Instructions and Additional Information 1. CH831502X08 ENG3171 2-04-15 TR# 125 TL# 20088 125A									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offor's Printed/Typed Name Jim Tyson									
Signature Jim Tyson									
Month Day Year 2/04/15									
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:								
	17. Transporter Acknowledgment of Receipt of Materials								
Transporter 1 Printed/Typed Name JACK CRNDORFF									
Signature Jack Crndorff									
Month Day Year 2/04/15									
Transporter 2 Printed/Typed Name									
Signature									
Month Day Year									
DESIGNATED FACILITY	18. Discrepancy								
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
	18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number								
	Facility's Phone:								
	18c. Signature of Alternate Facility (or Generator)								
Month Day Year									
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. H132 2. 3. 4.									
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
Printed/Typed Name Signature									
Month Day Year									

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number K50007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 485-3718	4. Manifest Tracking Number 008037596 FLE
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400			Generator's Site Address (if different than mailing address) SAME		
6. Transporter 1 Company Name U.S. Bulk Transportation Inc			U.S. EPA ID Number PA1987347515		
7. Transporter 2 Company Name			U.S. EPA ID Number		
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40355 S County Road 236 Wannoka, OK 73860 Facility's Phone: (580) 697-3500			U.S. EPA ID Number OKD065438376		
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity
			No.	Type	12. Unit Wt./Vol.
	x	1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III	1	DT	EST 16 Y
		2.			
		3.			
		4.			
13. Waste Codes					
					F001 F002 F003 F004 F005
14. Special Handling Instructions and Additional Information 1. CH831502X08 ERG#191 2-04-15 TR# 125 125A TL# 20088					
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.					
Generator's/Offoror's Printed/Typed Name Jim Tyson			Signature Jim Tyson		Month Day Year 12/04/15
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:				
	17. Transporter Acknowledgment of Receipt of Materials				
	Transporter 1 Printed/Typed Name JACK ORNDORFF			Signature Jack Orndorff	
	Transporter 2 Printed/Typed Name			Signature	
	18. Discrepancy				
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection				
DESIGNATED FACILITY	18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number				
	Facility's Phone:				
	18c. Signature of Alternate Facility (or Generator) Month Day Year				
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)				
	1. H132	2.	3.	4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a					
Printed/Typed Name Cindy Bradford			Signature Cindy Bradford		Month Day Year 12/04/15